



测高仪 Hi_Cal

描述

- 功能直观简洁
- 超强机动性
- 可测量内外径、中心距、高度、厚度、深度、平面间距
- 150和300 mm 两种测量范围
- 数据输出模式: USB 及 RS232

925.5609

926.6001

925.1142

926.5130



(


98


开机就可测量!



测高仪 Hi_Cal

图纸尺寸





面板功能

- 测量单位及当前基准系
- 2 测量值
- 3 当前测量模式
- 4 中心距
- 5 动态测量模式
- 6 直径/高度测量
- 7 进入系统设定菜单
- 8 选择基准系 Ref I / Ref II
- **9** 开/关机
- 10 测头常数
- 激活最小/最大值模式
- 12 有效测量指示灯







测高仪

Hi_Cal

技术参数

		830.0150	830.0300	
测量范围	mm			
	mm	150 300		
应用范围	mm	0 - 155 0 - 320		
最大允许误差	$\mu_{ ext{m}}$	2.5 + L / 175 ¹⁾		
重复性	$\mu_{ ext{m}}$	2		
分辨率	mm	0.01 / 0.001		
移动速度	mm/s	50 / 100		
测力	N	0.2 - 0.3		
电池连续工作时间	h	> 40		
高度	mm	379	529	
重量	kg	3.9	4.6	
数据输出接口		USB / mini USB / RS232 ²⁾		
电脑程序设置参数				
置零功能				
最小/最大/差值模式				
预设值功能				
2基准系				
测量高度、孔径和中心距				
两种移动速度		•		

¹⁾使用标配测头,在实验室条件下测量 ²⁾参考数据线部分

仪器配置

- HI_CAL 150 防尘罩
- HI_CAL 300 防尘罩
- 充电器 (930.40101) /11/12/13)
- 红宝石测头 Ø 3 mm
- 设定规
- 校准证书
- 操作手册

¹⁾ 依据国别而定





测高仪 Hi_Cal

应用



测量深度,选用附件930.2108 和930.2105



测量深度,选用附件930.2108 和905.2204




内孔测量,采用Ø3 mm红宝石测头,930.2101 (标配)




内沟槽测量,选用附件930.2108,930.2110和 905.2207




标定测头常数,借助设定规930.2002(标配)




高度及厚度测量,使用标配测头930.2101



内沟槽测量,选用附件 930.2108,930.2110 和905.2205



外径测量,使用标配测头 930.2101



最小值/最大值/差值测量






测高仪

Hi_Cal

附件表





测高仪 Hi_Cal

•

附件表

86.8 92 ±90° 02	930.2102	可旋转钨钢测头 (M1.4)
124 29 30 50 50 50 50 50	930.2109	延长杆 124 mm M2.5
62.5	930.2110	延长杆 80 mm M2.5
M2.5	905.2207	测头夹持器,带有 Ø 3 mm红宝石测头, M2.5
M2.5 M2.5 M2.5 O11.5	905.2205	碟形测头 Ø 7.7 mm 和Ø 11.5 mm, M _{2.5}
	930.2150	木盒全套附件套装 包括: 930.2103, 930.2104, 930.2105, 930.2106, 930.2107, 930.2108, 930.2109, 930.2110, 905.2204, 905,2205, 905.2207
	930.2151	木盒基本附件套装 包括:930.2103,930.2104,930.2105,930.2106
	904.4101	外接控制器(脚踏开关)

Catalogue_2013_CN.indb 103 17/07/2013 16:03:30